

10




FIG. 1

30- 30

Click NFuse - Microsoft Internet Explorer

File Edit View Favorites Tools Help

Back Forward Stop Refresh Home Search Favorites History Mail Print

Address http://kzists01/appended.asp?NFuse_EmbMethod=1&NFuse_Application=Closex0020Services002001.dats

Done

Service Order 300192

Arrival Date 12/7/00 Arrival Time 8:00 AM Completion Date 12/7/00 Completion Time 9:00 AM

Work Hours 1 Mileage 123 Weight Cost 0

Symptom Code Select CAP CLOGGED CAP TUBE

Repair Code Select CAP REPLACED CAP TUBE

Report Parts Used No Parts Used

Clear Forms Back

Exit

FIG. 2

TO9T20" E0540660

32

30

34

36

Microsoft Internet Explorer

File Edit View Favorites Tools Help

Back Forward Stop Refresh Home Search Favorites History Mail Print

Address http://kztsbs01/appembed.asp?NFuse_EmbedMethod=1&NFuse_Application=Close0020Sservice00200orders

Service Order 300192

Item Code Description Qty Reimbursement Price

RA19006	CONTROL BOARD ASSY ACR2000	1	621.03
RA19006	REPL. REFRIG. SOL. ASSY	2	47.47
103017	CARD WARRANTY 72-20 DISC	1	15.95

Enter Repair Taxi

Clear Form

Subtotal 731.92

Exit

FIG 3

09904503.071601




FIG. 4